

Route Risk Assessment

Service 11 Western Harbour - Hyvots Bank Central & Marine Garages

Provide details of any identified problems/issues and any control measures/special arrangements undertaken including vehicle type restrictions etc on separate sheet if required			Summarise details & locations	Likely impact of non-competent performance	Summary Controls	Location specific awareness information/training provided	Route learning will be provided to all drivers	Drivers encouraged to report incidents/problems	Control/ODD/Drivers engaged in monitoring/improvement	(Task performed competently)			Other - please detail	Resultant route risk level			
Do Any of the Statements listed below have any relevance to the route under review? <i>Tick as appropriate</i>	Yes	No								Severity	Likelihood	Risk rating		Intolerable	Undesirable	Tolerable	
Driver has sufficient visibility at any road junctions and/or roundabouts?	✓		Sufficient visibility at all road junctions and roundabouts. Care to be taken at Craighall / Stanley Road mini R/A as LH turn will require wide swing using full roundabout.	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, traffic circulars, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	2	3				3	
The route is free from overhanging branches or (or potential) on the route?		✓	1. Frogston road 2. Margaret Rose Gardens bus stop	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, Driver reporting procedure for on route hazards, traffic circulars developed and information posted in garages, route driven by qualified PCV drivers, risk awareness, LB Roads Hazard records	YES	YES	YES	YES	1	2	3	Incident review March 2022 - Buckstone Tce also identified as a repeat location for damage by overhanging trees. This has been flagged to BSI (delete) add 'All occasions monitored & IID liaise with tree owners to arrange cutting back as required.				3
Bus lanes bus / bus stops / roads appropriately defined & marked - Free from indiscriminate parking?		✓	All bus stops, lanes marked appropriately - Indiscriminate parking includes - 1 Newhaven Road 2. Stanley Road 3. Lothian Road 4. Home Street 5. Leven Street 6. Morningside Road 7. Comiston Road 8. Pilrig Street 9. Picardy Place (Coaches)	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, traffic circulars, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	2	1	3					3
Road restrictions or traffic speed/control measures visible and can be traversed safely (e.g. road humps)?	✓		All measures clearly visible throughout the route.	Driver speeding, vehicle damage, uncomfortable journey for passengers	Qualified PCV drivers, risk aware, customer engagement awareness	YES	YES	YES	YES	1	1	2					2
Timings reflect any congestion issues	✓		Queuing traffic taxis/parking. - peak times and weekend traffic as well as city events might impact timings	Drivers not operating to schedules, Drivers not trained, accidents,	Published service timetable, drivers have time board and AVL system within cab to inform when operating early/late, Qualified drivers, risk aware	YES	YES	YES	YES	1	1	2					2
Route (incl off service routes & normal diversions) suitable for all bus types?	✓		Yes this route is suitable for all vehicle types, including Tri Axle DD.	Wrong route driven, contact with stationary objects, contact with other road users, Double Deck bus possible contact with Balgreen (Low Bridge 14ft), Roseburn Street Low Bridge (12' 9"), New Street Low Bridge (10' 9"), Calton Road Low Bridge (10' 9"), Brand Place Low Bridge (13' 6"), Spring Gardens Low Bridge (13' 9")	Route risk assessment, Low bridge awareness campaign, Driver route training also includes off service routes, Management awareness posters.	YES	YES	YES	YES	2	1	3	Route information held within control room and schedules, Control room have 'Live' visibility of all vehicles being used on all routes to minimise risk of vehicles colliding with a Low Bridge - any/all incidents or near misses to be fully investigated and reported to Head of Operations/Head of Risk				3
No height restrictions i.e. low bridges etc on or close to the route?	✓		There are a number of low bridges near the service which may represent a danger if off route. These include Balgreen (Low Bridge 14ft), Roseburn Street Low Bridge (12' 9"), New Street Low Bridge (10' 9"), Calton Road Low Bridge (10' 9"), Brand Place Low Bridge (13' 6"), Spring Gardens Low Bridge (13' 9") This list may not be comprehensive - Full details are contained on LB Roads and Low Bridge awareness materials.	Wrong route driven, contact with stationary objects, contact with other road users, Double Deck bus possible contact with Balgreen (Low Bridge 14ft), Roseburn Street Low Bridge (12' 9"), New Street Low Bridge (10' 9"), Calton Road Low Bridge (10' 9"), Brand Place Low Bridge (13' 6"), Spring Gardens Low Bridge (13' 9")	Route risk assessment, Low bridge awareness campaign, CPC courses incl 2021 & 2024, Driver route training also includes off service routes INEO Install 2024	YES	YES	YES	YES	3	1	4	Route information held within control room and schedules, Control room have 'Live' visibility of all vehicles being used on all routes to minimise risk of vehicles colliding with a Low Bridge - any/all incidents or near misses to be fully investigated and reported to Head of Operations/Head of Risk -LB Roads & Diversionary notice alerts.				4

Provide details of any identified problems/issues and any control measures/special arrangements undertaken including vehicle type restrictions etc on separate sheet if required			Summarise details & locations	Likely impact of non-competent performance	Summary Controls	Location specific awareness information/training provided	Route learning will be provided to all drivers	Drivers encouraged to report incidents/problems	Control/OD/Drivers engaged in monitoring improvement	(Task performed competently)			Other - please detail	Resultant route risk level		
Do Any of the Statements listed below have any relevance to the route under review? <i>Tick as appropriate</i>	Yes	No								Severity	Likelihood	Risk rating		Intolerable	Undesirable	Tolerable
Are bus stops suitably positioned away from road junctions and other road/traffic hazards?	✓		All stops suitably positioned throughout this service	Drivers not adhering to designated bus stops	Drivers trained in stopping patterns during route learning	YES	YES	YES	YES	1	1	2				2
Bus stops, BSI and other fixed infrastructure far enough from kerb edges to allow safe entry / exit at bus stops?		✓	All bus stops are suitable positioned - Fixed street litter bin at foot of Lothian Road and Home Street, evidence of tailswing contact with other services - Comiston Road Northbound parking meter close to kerb edge, evidence of N/S mirror making contact - Euro bins kerb edge at various locations throughout this route - Street railings - Morningside Primary Middle door vehicles - customers must use front door	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	2	1	3	ALL LOCATIONS IDENTIFIED REPORTED TO IID TO SEEK IMPROVEMENT VIA LOCAL AUTHORITY AS PRACTICABLE			3
Kerbs heights along route do not cause access problems for passengers? / vehicles or restrict vehicles that may be used	✓		Kassel kerbs at various stops throughout the route	Drivers make contact with Kassel kerb when entering bus stop causing vehicle damage	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2				2
All roads used are public highways? (written permission and site specific risk assessment is required for any private roads accessed)	✓		All roads public highways	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2				2
There is no requirement for reversing of vehicles on the route?		✓	No reversing required in normal operation. If driver is required for unforeseen reasons to reverse, Control should be contacted to provide advice	Wrong route taken, driver reverses bus without banksman, damaged bus	Drivers must contact control when wrong route taken, Drivers should not be reversing buses on street	YES	YES	YES	YES	1	1	2				2
No excessively high numbers of school children use this route?	✓		Route passes a number of schools and children, young adults could be higher in these areas: Morningside Primary School - Gracemount High School	Wrong route taken, failure to pick up customers, company reputation, customer complaints, loss of revenue.	Route learning, driver training, route driven by qualified PCV drivers, risk awareness, road markings, signage, speed restrictions (20 mph)	YES	YES	YES	YES	2	1	3				3
Any expected higher than normal volumes of pedestrians at particular times or days?	✓		1. Morning, evening & weekend peaks 2. Edinburgh festival 3. Edinburgh Christmas & New Year celebrations 4. Edinburgh Marathon 5. Moonwalk 6. King's Theatre 7. City Sporting events.	Wrong route taken, failure to pick up customers, increase in pedestrian accidents	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	2	1	3				3
No evidence of assaults / vandalism occurring on services in areas served		✓	Known ASB Hotspots across Network - incl Hyvots - Captains Road on route	Driver confronts youths, escalates the problem, delays service, customer complaints, driver gets hurt, vehicle damage	Driver training, control room procedures, record and report to Police liaison officer	YES	YES	YES	YES	3	1	4	Vehicle design features include: Driver safety screen, radio and emergency alarms on all vehicles - additional measures - H&S Dept, Police liaison officer to monitor assault and vandalism data, increased levels of vandalism during Covid pandemic			4
Layover and WC facilities suitable and sufficient	✓		Asda Western Harbour - Newhaven	Driver unable to access toilet facilities	Driver issued a key to access toilets on route, agreement in place with council buildings for drivers to use facilities	YES	YES	YES	YES	1	1	2				2
No evidence to indicate high numbers of passengers with special needs / vulnerability and/or disabilities use this route?		✓	Large numbers of elderly and vulnerable use service for social activities	Harsh braking events, rise in customer complaints, injuries and compensation claims	Route learning, driver training, route driven by qualified PCV drivers, risk awareness, CPC continuous training	YES	YES	YES	YES	2	1	3				3

Provide details of any identified problems/ issues and any control measures/special arrangements undertaken including vehicle type restrictions etc on separate sheet if required			Summarise details & locations	Likely impact of non-competent performance	Summary Controls	Location specific awareness information/training provided to all drivers	Route learning will be provided to all drivers	Drivers encouraged to report incidents/problems	Control/CI/D/Drivers engaged in monitoring improvement	(Task performed competently)			Other - please detail	Resultant route risk level			
Do Any of the Statements listed below have any relevance to the route under review? <i>Tick as appropriate</i>	Yes	No								Severity	Likelihood	Risk rating		Intolerable	Undesirable	Tolerable	
Bus lanes suitably marked, signed & wide enough for vehicles to use?	✓		All bus lanes marked and suitable for use	Drivers make contact with kerb stationary or other road users	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2				2	
Route reviewed in dark and street and/or vehicle lighting levels considered suitable		✓	Route reviewed during daylight hours - No Noted issues with low light operations.	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2	Incidents & Driver reports monitored by Insurance and Garage management if there is an increased accident rate for services driving during darkness hours an assessment may be required				2
All drivers have received both route and vehicle familiarisation training for this route and been advised of special arrangements for hazards identified?	✓		Full route training provided. New drivers will be supported by Lead Drivers. Video route is available on Lothian training "YouTube" channel	Wrong route driven, contact with stationary objects, contact with other road users	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2	Video- Route & RRA Awareness review 2023				2
Manual handling training given (ramp operation) Tick as appropriate	✓		Training given to all drivers on how to use manual ramp	Unable to serve disabled customers needs	Route learning, driver training, route driven by qualified PCV drivers, risk awareness	YES	YES	YES	YES	1	1	2					2
Potential impact of adverse weather and access to gritting plans appropriately considered with outcomes communicated		✓	Potential for route to be subject to ice / snow. All drivers trained & experienced in area with rasios. Existing Control Room response procedures will apply. Control Room Staff have Gritting Plans	Driver operates vehicle in unsafe conditions	Services operate on main roads that are gritted any roads that are not cleared or driveable services will be curtailed or stopped	YES	YES	YES	YES	2	1	3	Gritting plans required from local authority annually				3
Is the route approved for rear door operation and Tri-axle vehicles and suitable? Tick as appropriate		✓	Tri-Axle bus has been assessed and is suitable for this route - Middle door exit Cannot be used at Morningside primary due to street railings - other limitations held at garage.	Wrong route driven, contact with stationary objects, contact with other road users, Double Deck bus possible contact with Balgreen (Low Bridge 14ft), Roseburn Street Low Bridge (12' 9"), New Street Low Bridge (10' 9"), Calton Road Low Bridge (10' 9"), Brand Place Low Bridge (13' 6"), Spring Gardens Low Bridge (13' 9")	Route risk assessment, Low bridge awareness campaign, CPC course 2021. Driver route training also includes off service routes	YES	YES	YES	YES	2	1	3					3
All other route specific risks identified and controlled?	✓		Crosswinds at Fairmilehead to Kaimies Crossroads.	Staff, customers put at risk	H&S dept. company risk assessments, route risk assessments	YES	YES	YES	YES	1	1	2					2
Assessors: Pat Toner, Stephen O'Hara										Date: 2nd September 2024							
Approved by: Walter Herring, Craig McCafferty, Katrina Scott										Date: 2nd September 2024							

Note - For risk levels that are Undesirable or Intolerable additional control measures or action should be taken/considered to reduce the risk to Tolerable so far as reasonably practicable