

Driver Defect Report

| | | | |
|---------------------------------|-------------------|----------------------------|---------|
| Code 4922481 | | Date 09/03/2021 Time 09:03 | |
| Fleet No | 1073 | Reg No | SJ190WH |
| Employee No | 659382 | Liam Smith | |
| Repairing Location | LB CENTRAL GARAGE | Route No 16 | |
| Incident Location | LEOPOLD PLACE | Route Block No 112 | |
| Fault | | Class | |
| 667 WINDOW - SOILED DAMAGED | | 1CC Changeover - Central | |
| Additional Defect Information | | | |
| L/S N/S 3RD REAR WINDOW CRACKED | | | |
| CHECKED BY P1 | | | |
| C/O 11.14 | | | |

Previous Defects

| Date | Time | Defect | Fault (1) | Fault (2) | Status |
|------|------|--------|-----------|-----------|--------|
|------|------|--------|-----------|-----------|--------|

Repair Details Fault 1

| | | | |
|------------------|-----|-------------------------|--|
| Name & No. | | | |
| Fault Code | 667 | WINDOW - SOILED DAMAGED | |
| Repair Full Info | | | |
| Cleared By | | | |
| Comp Date | | Comp Time | |

Repair Details Fault 2

| | | | |
|------------------|--|-----------|--|
| Name & No. | | | |
| Fault Code | | | |
| Repair Full Info | | | |
| Cleared By | | | |
| Comp Date | | Comp Time | |